

















# Instrukcja Montażu


profim


ASSEMBLY INSTRUCTION - UpDown (linking parts)  
 MONTAGEANLEITUNG - UpDown (Reihenverbinder)  
 INSTRUKCE K MONTÁŽI - UpDown (konektory)  
 INSTRUCTION DU MONTAGE - UpDown (connecteurs)  
 ИНСТРУКЦИЯ ПО СБОРКЕ - UpDown (соединителя)


UpDown  
 (łączniki)

|  |  |  |  |  |   |
|--|--|--|--|--|---|
| <b>A</b><br><br>2 x | <br>10  | <br>11  | <br>12  | <br>20  | <br>2L  |
|  | <br>2R  | <br>C40 | <br>C41 | <br>C42 | <br>C43 |
| <b>B</b><br><br>4 x | <br>B10 |  |  |  |   |
| <b>C</b><br><br>4 x | <br>C10 | <br>C20 |  |  |   |


**1**









**A**  
  
 2 x

~~B10 B10~~


**B**  
  
 4 x

**M043**








2





4x




3



1




1



2

4x



C